



International Carwash Association

Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

General Motors 2007 Full Size SUV Rear Door Outer Belt Sealing Strip

The rear door outer belt sealing strip molding on the 2007 Chevrolet Tahoe, GMC Yukon and Yukon Denali can come loose..

The problem is that there may be a lack of adhesive between the window run channel and the outer belt sealing strip which can contribute to this condition.

To correct this condition, General Motors has published Service Bulletin No. 06-08-64-026A to replace the rear door outer belt sealing strip with a new designed part.

If the subject condition occurs in your car wash, direct the owner of the vehicle to return to their dealership where a new rear door outer belt sealing strip will be installed at no cost to the owner.

If you have any questions, please contact the International Carwash Association at ica@smithbucklin.com.