



**International Carwash Association**  
*Your Partner for Success*

401 N. Michigan Avenue  
Chicago, Illinois 60611-4267  
**Phone: 312-321-5199**  
Fax: 312-245-1085  
e-mail: [info@carwash.org](mailto:info@carwash.org)  
[www.CarWash.org](http://www.CarWash.org)

**FOR IMMEDIATE RELEASE**

**Vehicle Damage Alert:  
GM Full Size SUV High Mount Stop Lamp Housing**

**CHICAGO, IL – May 23, 2007** - General Motors has reported that possible damage might occur to the high mount rear stop lamp housing located above the rear window on certain GM full size SUV's in a car wash.

The vehicles affected are the 2007 Chevrolet Suburban and Tahoe and the 2007 GMC Yukon, Yukon XL and Yukon Denali models built between September 28, 2006 and November 3, 2006. The attachment of the high mount stop lamp housing has been revised and should not be a problem on vehicles built after November 3.

General Motors has notified their dealers advising them that if this damage should occur on the affected vehicles the repair will be covered under the vehicle warranty.

Please visit [www.carwash.org/OperatorInformation/VehicleDamageCenter](http://www.carwash.org/OperatorInformation/VehicleDamageCenter) to report vehicle damage occurring at your wash and share all issued Vehicle Damage Alerts with your staff.

If you have any questions, please contact the International Carwash Association at (312) 321-5199 or [info@CarWash.org](mailto:info@CarWash.org).

Joe Ward  
Director of Engineering  
International Carwash Association